


## Vibration cut out switch

## Spare parts guide

## Vibration cut out switch

- The switch **detects excessive fan drive vibration** caused by fan icing or any mechanical fault.
- Mechanical operation with multiple options for alarms and reset.
- Guarantees year-round reliable and safe operation.





## **Downloads**

• The SERVICE EXPERT for BAC Equipment